

Contact: Rohan Thorogood
Direct Line: 0427 924 815
Our ref: 08-002621/002 Doc 2245136
Your ref:



SunWater Limited
Level 10, 179 Turbot Street
PO Box 15536 City East
Brisbane Queensland 4002
www.sunwater.com.au
ACN 131 034 985

10 November 17

Dear Landholder

Moolabah Weir Operating Level

Due to issues at the Thuraggi Outlet at Beardmore Dam, SunWater is in the process of altering the operational level of Moolabah Weir in an effort to mitigate the issues at the Dam. The new full supply level of the weir will be approximately 0.7m higher than the current full supply level.

SunWater intend on maintaining the level in Moolabah Weir at or near 202 m AHD (0.7m higher than current) when E J Beardmore Dam is above 75%. As this is 70 centimetres above the current operating level, as a landholder adjacent to ponded area of Moolabah Weir, SunWater request:

1. That you make sure your pumping infrastructure is above a minimum level of 202.2 m AHD, or approximately 90 centimetres above the current operating level; or
2. Notify SunWater by Friday 17 November 2017 if you require any assistance in raising your pumping infrastructure to the necessary level.

Should no enquiries be received, SunWater intend to operate Moolabah Weir above 201.3 m AHD from 17 November 2017. Please contact me at 0427 924 815 if there are any queries on the above.

Yours sincerely

Rohan Thorogood
Service Manager –St George